

SCHOOL FITNESS CERTIFICATE

File No . E1-893879/2025

To be filled by the Inspecting Officer (Asst. Engineer)
(Re: G.O. Ms. 20/70/PWD Dt. 23-01-1970)

- 1 Name of School :- Christuraja Public School,vellaramkundu
- 2 Name of Officer :- MUNAVAR K
- 3 Location :- Kalpetta
- 4 Period of which the certifiacte issued :- 2025-2026
- 5 Type of Building :- Permanent
- Basement floor
9.52x6.33x3.52 (Biology Lab)
9.52x6.26x3.52 (Computer Lab)
6.43x6.35x3.52 (Class room)
6.28x6.30x3.52 (Mathematics Lab)
12.82x6.30x3.52 (Physics Lab)
12.74x6.30x3.52 (Chemistry Lab)
- Ground floor
9.50x12.27x3.67 (Library)
6.35x6.29x3.67 (Class Room)
6.38x6.31x3.67 (Staff Room)
6.23x6.31x3.67 (Principal Room)
6.42x6.31x3.70 (Office Room)
6.35x6.31x3.67 (2 Class Room)
- New block I
26.60x8.90x3.40 (3 Class Room, Toilet)
26.60x8.90x3.40 (3 Class Room, Toilet & Staff Room)
26.60x8.90x3.40 (Hall , Toilet)
- 6 Nature of defect if any :- Nil
- a) Foundation and basement
- b) Super structure
- c) Doors and Windows
- d) Woodwork wrought and put up
- e) Roof
- f) Flooring
- g) Miscellaneous
- 7 Any major defects notice which will render the building unsafe in any manner :- No
- 8 Whether maintenance works have been done properly :- Yes


9 Whether the structure is found for conducting classes :- Safe Under Normal Climatic Condition


The stability of the structure should be examined also with reference altitude, intensity of wind exposure to flood etc.

Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate

Certificate that the School was inspected by on 20/05/2025 and found to be fit to conduct classes for the period for the reason stated above

Kalpetta
22-05-2025




MUNAVAR K
ASSISTANT ENGINEER LID&EW
KALPETTA
LSGD Kalpetta Municipality
PEN:440201 Mob#9961621516